



**Subj: End of Life (EOL) Notice for FEI-Zyfer AccuSync II® Model 405 GPS Time and Frequency Systems**

Dear Valued Customer:

Please consider this letter as official notification of FEI-Zyfer' s intent to discontinue production of our AccuSync II ® Model 405 GPS Time and Frequency Systems effective immediately.

The standard warranty terms will be honored for all AccuSync II systems that are still within the warranty period. For out of warranty systems, repairs will be limited by availability of replacement parts on hand. Telephone and email technical assistance will still be provided to AccuSync II customers.

AccuSync II Products Affected by End of Life (EOL):

<b><u>Part Number</u></b>	<b><u>Description</u></b>
405011101	ASSEMBLY, ACCUSYNC II, C/A, OCXO AC, DDS/HQ/IRIG/BCD, 6 10MHZ, 4 5MHZ
405011102	ASSEMBLY, ACCUSYNC II, C/A, OCXO AC, 6 10MHZ
405011201	ASSEMBLY, ACCUSYNC II, C/A, OCXO 36V-72VDC, DDS/HQ/IRIG/BCD, 6 10MHZ, 4 5MHZ
405011301	ASSEMBLY, ACCUSYNC II, C/A, OCXO 10V-36VDC, DDS/HQ/IRIG/BCD, 6 10MHZ, 4 5MHZ
405012101	ASSEMBLY, ACCUSYNC II, C/A, RB, AC, DDS/HQ/IRIG/BCD, 6 10MHZ, 4 5MHZ
405012201	ASSEMBLY, ACCUSYNC II, C/A, RB, 36V-72VDC, DDS/HQ/IRIG/BCD, 6 10MHZ, 4 5MHZ
405012301	ASSEMBLY, ACCUSYNC II, C/A, RB, 10V-36VDC, DDS/HQ/IRIG/BCD, 6 10MHZ, 4 5MHZ

Reason for EOL: Obsolescence of third party components used to build the AccuSync II

Last Purchase Date: 25 May 2016

Replacement/Alternative Product(s): GSync ® and/or CommSync II® GPS Time and Frequency Systems

If you have any questions or for assistance in selecting alternative products, please visit our website at [www.feizyfer.com](http://www.feizyfer.com) or contact us by phone 714-933-4002 or by email at [sales@feizyfer.com](mailto:sales@feizyfer.com).

Sincerely,

FEI-Zyfer, Inc.