

January 20, 2025

Subj: Update to End of Life (EOL) Notice / New End of Repair (EOR) Notice for FEI-Zyfer GPStarplus ® Model 565 GPS Time and Frequency Systems**Ref: Original GPStarplus EOL Notice dated 30 September 2023.**

Dear Valued Customer:

Please consider this letter as official notification of FEI-Zyfer's intent to discontinue production of **and** notification of the end of repair services for our GPStarplus ® Model 565 systems effective immediately.

Due to third-party component obsolescence, FEI-Zyfer can no longer build new GPStarplus systems or repair existing systems outside of warranty coverage.

Telephone and email technical assistance will still be provided to GPStarplus customers. However, Return Material Authorization (RMAs) will not be issued for factory repairs.

GPStarplus Products Affected by this End of Life (EOL) / End of Repair (EOR):

<u>Part Number</u>	<u>Description</u>
565021001	ASSEMBLY, GPSTARPLUS (AC IN/OCXO/NO OPTIONS)
565021002	ASSEMBLY, GPSTARPLUS (AC IN/OCXO/NO OPTION/DC BLOCK)
565021101	ASSEMBLY, GPSTARPLUS (AC INPUT/OCXO/DDS OPTION)
565021201	ASSEMBLY, GPSTARPLUS (AC INPUT/OCXO/QUAD LPN 10MHZ OPTION)
565022001	ASSEMBLY, GPSTARPLUS (DC INPUT/OCXO/NO OPTION)
565022101	ASSEMBLY, GPSTARPLUS (DC INPUT/OCXO/DDS OPTION)
565023001	ASSEMBLY, GPSTARPLUS (HI VDC IN/OCXO/NO OPTIONS)
565031001	ASSEMBLY, GPSTARPLUS (AC IN/RB OSC/NO OPTIONS)
565031101	ASSEMBLY, GPSTARPLUS (AC IN/RB OSC/DDS OPTION)
565033001	ASSEMBLY, GPSTARPLUS (HI VDC IN/RB OSC/NO OPTIONS)

Reason for EOL: Obsolescence and lack of support for third party components used to build the GPStarplus
Last Purchase Date: 30 Sep 2023

Replacement/Alternative Product(s): GSync ® and/or CommSync II® GPS Time and Frequency Systems

If you have any questions or for assistance in selecting alternative products, please visit our website at www.fei-zyfer.com or contact us by phone 714-933-4002 or by email at sales@fei-zyfer.com.

Sincerely,

FEI-Zyfer, Inc.